


AREA PELIGROSA. PARTES MOVILES. MARCAR EL
CONTORNO CON FRANJAS AMARILLAS Y NEGRAS. /
DANGEROUS AREA. MOVING PARTS. MARK THE
CONTOUR IN BLACK-YELLOW STRIPS.

PERFORMER-2000

X: 2000 Y: 1000 Z: 1100



DPTO. TECNICO
SALIDA
FECHA: 17/01/07

240021



ITZIAR-DEBA

Escala	Formato	Db. Rev.	J.A. P.G.	Fecha
1:25	A3			17/01/05
				17/01/05
Designacion				Nº de plano
PERFORMER-2000 Y-1000 (CON CAJA DE REDUCCION).				C-240902035-0
CARENADO. EXTRACTOR. CNC COLGANTE.				